



Product Change Notification

108206 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

America's OEM's Contact:

Lester Dimit

Phone:(503) 712-8272

Email: lester.dimit@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108206 - 01
Change Title: Intel® Wireless WiFi Link 4965AGN Skus: 4965AGNMM1GN, M2GN, RWGN, JPGN, JPGN0, KRGN, 4965AG_MM1GN, M2GN, RWGN, JPGN, JPGN2, KRGN, PCN 108206-01, Label, OUI Replenishment, Reason for Revision: Correction to TA# dash change on the 4965AG_MM2GN SKU
Date of Publication: May 07, 2008

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 25, 2008
Date of First Availability of Post-Conversion Material:	Jan 25, 2008

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Reason for Revision: Correction to TA# dash change on the 4965AG_MM2GN SKU

Update to MAC Address: Incorporate new OUI block on 4965AGN and 4965AG_ SKUs as current OUI block will soon be depleted.

Current	New
00 - 1D - E0	00 - 1F - 3B

Customer Impact of Change and Recommended Action:

Customer will receive product with the following changes:

1. New MAC addresses with a change in the first 6 characters. Refer to the below table for the affected product codes.

Current	New
00 – 1D – E0	00 – 1F – 3B

2. Dash to the TA#

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

For your information only. No change to form fit or function. No change to Intel Ordering codes.

Milestone dates are estimates and subject to change based on business and operational conditions.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
4965AGNMM1GN	886224	886224	D73379-011	D73379-012	D65465-006	D65465-006
4965AGNMM2GN	886220	886220	D73380-011	D73380-012	D65465-006	D65465-006
4965AGNMRWGN	886434	886434	D73381-010	D73381-011	D65465-006	D65465-006
4965AGNMJPGN0	891353	891353	E11063-005	E11063-006	D65465-006	D65465-006
4965AGNMJPGN	886437	886437	D73382-013	D73382-014	D65465-006	D65465-006
4965AGNMKRGN	888121	888121	D82807-005	D82807-006	D65465-006	D65465-006
4965AG_MM1GN	886449	886449	D74671-008	D74671-009	D65465-006	D65465-006
4965AG_MM2GN	886450	886450	D74672-007	D74672-008	D65465-006	D65465-006
4965AG_MRWGN	886451	886451	D74673-008	D74673-009	D65465-006	D65465-006
4965AG_MJPGN	886461	886461	D74674-011	D74674-012	D65465-006	D65465-006
4965AG_MJPGN2	892228	892228	E15263-005	E15263-006	D65465-006	D65465-006
4965AG_MKRGN	886733	886733	D74709-004	D74709-005	D65465-006	D65465-006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

January 8, 2008

00

Originally Published PCN

May 7, 2008

01

Correction to TA# dash change on the 4965AG_MM2GN SKU